


CAUTION! DO NOT THROW



Error F2 – Overload Recovery Procedure

1. Insert foot into foot cup to open lid, switch-Off macerator with lid opened.
2. Remove ALL items inside chamber thoroughly.
3. Pour one pail of water into chamber to clear debris.
4. Switch-On macerator, start macerator cycle by placing hand over the “START” sensor.
5. If error persists, call service Hotline **6817 8967**



email: sales@neuindustries.com
www.neuindustries.com